DISTRICT EIGHT

FOLK GRADLY MEATH MEARINENT

DIRECT SERVICE UNITS

1755 HOLLAND PKWY., SOUTH BARTOW, FLORIDA 33830

111 NORTH 11TH STREET HAINES CITY, FLORIDA 33844

305 WEST CENTRAL AVENUE LAKE WALES, FLORIDA 33853

103 EAST CANAL STREET MULBERRY, FLORIDA 33860

WILLIAM F. HILL, JR., M.D.

P.O. BOX 1480 229 AVENUE D, N.W. WINTER HAVEN, FLORIDA 33880

Radiological And Occupational Health Post Office Box 1480 Winter Haven, Florida 33880 DIRECT SERVICE UNITS

1333 NORTH FLORIDA AVENUE LAKELAND, FLORIDA 33801

P.O. BOX 33 WAVERLY, FLORIDA 33877

2 NORTH REEDY BLVD. FROSTPROOF; FLQRIDA 33843

243 E. LAKE AVENUE AUBURNDALE, FLORIDA 33823

May 16, 1979

Rad. Health/ Field Survey

SITE: <i>£10</i>	uda	Phos	phote
BREAK:	11.8	,	
OTHER:	- 1/-	19	1 1 y s

Thomas F. Brannen Branco Enterprises, Inc. 600 Brannen Road Post Office Box 5197 Lakeland, Florida 33803

Dear Mr. Brannen:



This tract of land was surveyed by our department on December 30, 1977 as requested by another corporation. The readings recorded on the enclosed sketch indicate gamma radiation detected in microroentgens per hour (micro R/hr). These measurements ranged from 8 to 20 microroentgens per hour with an average level of 12.86 micro R/hr. The Environmental Protection Agency issued an interim guideline for construction on reclaimed land which states that if the external gamma levels are equal to or exceed 10 micro R/hr. then residential construction should be delayed pending additional study or an acceptable form of radon control technology should be initiated.

I have enclosed a copy of an Environmental Protection Agency document which discusses various radon control parameters which may help to answer any further questions on this matter.

If we can be of further help please feel free to contact us:

Radiological And Occupational Health Post Office Box 1480 Winter Haven, Florida 33880

Sincerely.

Keith B. Moore

Keith B. Moore Industrial Hygienist I